



Table of Contents



- [\(i\) Core or Iron Losses \(Pi\):](#)
 - [Hysteresis Loss:](#)
 - [Eddy Current Loss:](#)
- [\(ii\) Copper Losses \(Pc\):](#)
 - [Total Copper Loss](#)
- [Efficiency of a Transformer](#)
- [Full load Efficiency =](#)
- [Condition for Maximum Efficiency:](#)
- [Total copper loss \(Pc\)](#)
- [Transformer efficiency \(\$\eta\$ \)](#)
- [Types of Losses in Transformer](#)

The power losses in a transformer are of two types:

1. **Core or Iron Losses (Pi)**
2. **Copper Losses (Pc)**

(i) Core or Iron Losses (Pi):

Iron or core losses consist of: P_i

$$P_i = \text{Hysteresis loss} + \text{Eddy current loss}$$
$$\quad = \text{Constant losses}$$

These can be determine by **open circuit test** .

- These occur in the Transformer core due to the **alternating flux**.

Hysteresis Loss:

- **Hysteresis Loss:** $K_h f \mathit{B}_m^{1.6} \text{ watt/m}^3 = K_h f \mathit{B}_m^{1.6} V$

where:



- K_h = Hysteresis coefficient or Steinmetz constant
- f = frequency or no of cycles of magnetizing
- B_m = maximum flux density in the magnetic material
- V = volume of magnetic material

Eddy Current Loss:

- **Eddy Current Loss:**

$$K_h f^2 B_m^2 t^2 \text{ watt/m}^3 = K_h f^2 B_m^2 t^2 V$$

where:

- K_e = coefficient of the eddy current
- f = frequency of reversal of the magnetic field
- B_m = maximum flux density in the magnetic material
- V = volume of magnetic material
- T = Thickness of material / Lamination

* The hysteresis loss can be minimized by using steel of high silicon content, whereas eddy current losses can be reduced by using cores of thin laminations.

Minimization of Hysteresis Loss and Eddy Current Loss:

- Hysteresis loss → reduced by using **steel with high silicon content**
- Eddy current loss → reduced by using **thin laminations** in the core

(ii) Copper Losses (P_c):

These occur in both the primary and secondary windings due to ohmic resistance. They are variable losses and can be determined by the **short-circuit test**.

Total Copper Loss

$$P_c = I_1^2 R_1 + I_2^2 R_2$$



$$= I^2 R_{eq} \quad \text{(referred to secondary)}$$

Total Loss in a Transformer: -

$$P_i + P_c = \text{Constant losses} + \text{Variable Losses}$$

Efficiency of a Transformer

$$\text{Efficiency } (\eta) = \frac{\text{Output Power}}{\text{Input Power}}$$

$$= \frac{\text{Output Power}}{\text{output Power Losses}}$$

$$= \frac{\text{Output Power}}{\text{output Power} + \text{Copper loss} + \text{core loss}}$$

$$= \frac{\text{Output Power}}{\text{output Power} + P_c + P_i}$$

Full load Efficiency =

$$(\eta)_{FL} = \frac{\text{Full Load } V_a \text{ last } P_f}{(\text{Full Load } V_a \text{ last } P_f) + P_c + P_i}$$

Condition for Maximum Efficiency:

$$\text{Output Power} = V_2 I_2 \cos \phi_2$$

If R_{02} is the total resistance of the transformer referred to secondary then,

Total copper loss (P_c)

$$P_c = I_2^2 R_{02}$$

\

$$\text{Total Loss} = P_i + P_c$$

Therefore,



Transformer efficiency (η)

$$\eta = \frac{\text{Output Power}}{\text{Input Power}}$$

$$\eta = \frac{V_2 I_2 \cos \phi_2}{V_2 I_2 \cos \phi_2 + P_c + P_i}$$

$$\eta = \frac{V_2 I_2 \cos \phi_2}{V_2 I_2 \cos \phi_2 + I_2^2 R_{02} + P_i}$$

$$\eta = \frac{\frac{V_2 I_2 \cos \phi_2}{I_2}}{\frac{V_2 I_2 \cos \phi_2 + I_2^2 R_{02} + P_i}{I_2}}$$

$$\eta = \frac{V_2 I_2 \cos \phi_2}{V_2 I_2 \cos \phi_2 + \frac{P_i}{I_2} + I_2 R_{02}}$$

$V_2 \cos \phi_2$ is approximately constant. For two loads, of given power factor, efficiency depends upon load current I_2 . So, numerator is constant and the efficiency to be maximum, the denominator should be minimum.

$$\frac{d(V_2 \cos \phi_2 + \frac{P_i}{I_2} + I_2 R_{02})}{dI_2}$$

$$\Rightarrow \frac{0 + (-\frac{P_i}{I_2^2}) + 1 \cdot R_{02}}{1} = 0$$

$$\Rightarrow -\frac{P_i}{I_2^2} = -R_{02}$$

$$\Rightarrow P_c = I_2^2 R_{02}$$

Core loss = copper loss (Proved).

Hence,



efficiency of a transformer will be maximum when copper losses are equal to constant core losses.

Output KVA for maximum efficiency = $\text{Full Load KVA} \sqrt{\frac{\text{Iron Loss}}{\text{Full Load Copper Loss}}}$



Types of Losses in Transformer

1. Hysteresis Loss (P_h):

$$P_h = K_h f B_m^{1.6} V_e$$



2. Eddy Current Loss (P_e):

$$P_e = K_e f^2 B_m^2 t^2 V$$

3. Copper Loss (P_c):

$$P_c = I_1^2 R_1 + I_2^2 R_2$$

or (referred to secondary):

$$P_c = I_1^2 R_{01} + I_2^2 R_{02}$$

4. Total Losses:

$$\text{Total Losses} = P_i + P_c$$

$$\text{Total Losses} = \text{Constant Losses} + \text{Variable Losses}$$