



Parameter	Symbol / Formula	Where
<b>Primary EMF Equation of Single Phase Transformer (<math>E_p</math>)</b>	$E_p = 4.44 f N_p \Phi_m$	$f$ = frequency $N_p$ = Number of primary turns $\Phi_m$ = maximum flux
<b>Secondary EMF Equation (<math>E_s</math>)</b>	$E_s = 4.44 f N_s \Phi_m$	$f$ = frequency $N_s$ = Number of secondary turns $\Phi_m$ = maximum flux
<b>Transformation ratio (K)</b>	$\frac{N_s}{N_p} = \frac{V_s}{V_p} = \frac{I_p}{I_s} = K$	$N_s$ = Number of secondary turns $N_p$ = Number of primary turns $V_p$ = Primary voltage $V_s$ = Secondary voltage
<b>Turn Ratio</b>	$\frac{N_p}{N_s} = \frac{V_p}{V_s}$ $I_0 = \sqrt{I_m^2 + I_w^2}$	$N_s$ = Number of secondary turns $N_p$ = Number of primary turns $V_p$ = Primary voltage $V_s$ = Secondary voltage
<b>No load Primary Current (<math>I_0</math>)</b>		$I_m$ = Magnetising Component $I_w$ = Active or Working or Iron loss component
<b>Active or Working or Iron loss component (<math>I_w</math>)</b>	$I_w = I_0 \cos \phi_0$	$\phi_0$ = Angle between $V_p$ and $I_0$
<b>Magnetising Component (<math>I_m</math>)</b>	$I_m = I_0 \sin \phi_0$	$\phi_0$ = Angle between $V_p$ and $I_0$
<b>Impedance Ratio</b>	$\frac{Z_2}{Z_1} = K^2$ $\frac{R_2}{R_1} = K^2$ $\frac{X_2}{X_1} = K^2$	$Z_2$ = Secondary Impedance $Z_1$ = Primary Impedance
<b>Shifting in a Transformer (Referred to Primary)</b>	$R_{01} = R_1 + R_2'$ $X_{01} = X_1 + X_2'$ $Z_{01} = \sqrt{R_{01}^2 + X_{01}^2}$ $V_2' = \frac{V_2}{K}$ $I_2' = I_2 K$	$R_{01}$ = Equivalent resistance referred to primary $X_{01}$ = Equivalent reactance referred to primary $Z_{01}$ = Equivalent impedance referred to primary $R_2'$ = Secondary resistance referred to primary $X_2'$ = Secondary reactance referred to primary $V_2'$ = Secondary voltage referred to primary $I_2'$ = Secondary current referred to primary
<b>Shifting in a Transformer (Referred to Secondary)</b>	$R_{02} = R_2 + R_1'$ $X_{02} = X_2 + X_1'$ $Z_{02} = \sqrt{R_{02}^2 + X_{02}^2}$ $V_1' = \frac{V_1}{K}$ $I_1' = \frac{I_1}{K}$	$R_{02}$ = Equivalent resistance referred to secondary $X_{02}$ = Equivalent reactance referred to secondary $Z_{02}$ = Equivalent impedance referred to secondary $R_1'$ = Primary resistance referred to secondary $X_1'$ = Primary reactance referred to secondary $V_1'$ = Primary voltage referred to secondary $I_1'$ = Primary current referred to secondary



Parameter	Symbol / Formula	Where
		$V_{nl}$ = No load secondary voltage $V_{fl}$ = Full load secondary voltage
Percentage Voltage Regulation	$1) \%Reg_{\text{down}} = \frac{V_{nl} - V_{fl}}{V_{nl}} \times 100\%$	***** <b>Voltage regulation-down (<math>Reg_{\text{down}}</math>):</b> This happens when the secondary transformer terminal's voltage output decreases due to a load attached to it. <b>Voltage regulation-up (<math>Reg_{\text{up}}</math>):</b> This occurs when the secondary terminal of the transformer experiences an increase in voltage upon removal of the load.
	$2) \%Reg_{\text{up}} = \frac{V_{nl} - V_{fl}}{V_{fl}} \times 100\%$ <p>***** (1) No. equation is generally used</p>	
Voltage Regulation for lagging and leading	<b>For lagging p.f</b> $V_{nl} - V_{fl} = I_2 R_{02} \cos\phi_2 + I_2 X_{02} \cos\phi_2$ <b>For lagging p.f</b> $V_{nl} - V_{fl} = I_2 R_{02} \cos\phi_2 - I_2 X_{02} \cos\phi_2$	$R_{02}$ = Equivalent resistance referred to secondary $X_{02}$ = Equivalent reactance referred to secondary
Power (Ideal Transformer)	$(P_p = P_s)$ or $(V_p \cdot I_p = V_s \cdot I_s)$	$(P_p)$ and $(P_s)$ are the primary and secondary powers, $(V_p, V_s)$ are the voltages, $(I_p, I_s)$ are the currents.
Copper Loss ( $P_{cu}$ )	$(P_{Cu}) = I_p^2 R_p + I_s^2 R_s$	$I_p, I_s$ are the currents, $R_p, R_s$ are the resistances of primary and secondary windings
Core Loss or Iron loss	$(P_i = P_h + P_e)$	$P_i$ = Total core loss $P_h$ = Hysteresis loss $P_e$ = eddy current loss
Total losses in Transformer	Total losses $= P_i + P_{cu}$ $= \text{Constant Loss} + \text{Variable Loss}$	$P_i$ = Total core loss or Constant loss $P_{cu}$ = Copper loss or Variable loss
Hysteresis loss (in watts) ( $P_h$ )	$(P_h = \eta B_{\text{max}}^x f v)$	$\eta$ = Steinmetz hysteresis coefficient (depends on the material) $B_{\text{max}}$ = Maximum flux density in the core $f$ = Frequency of the magnetic field (in hertz) $v$ = Volume of the core (in cubic meters)
Eddy current loss (in watts) ( $P_e$ )	$(P_e = k_e B_{\text{max}}^2 f^2 t^2 v)$	$k_e$ = Constant that depends on the material's resistivity and geometry $B_{\text{max}}$ = Maximum magnetic flux density (in teslas) $f$ = Frequency of the magnetic field $t$ = Thickness of the core laminations (in meters) $v$ = Volume of the core (in cubic meters)
Efficiency ( $\eta$ )	$(\eta = \frac{P_{\text{out}}}{P_{\text{in}}} \times 100\%)$ $(\eta = \frac{P_{\text{out}}}{P_{\text{out}} + \text{Losses}} \times 100\%)$	$P_{\text{out}}$ = Output power, $P_{\text{in}}$ = Input power.